

SPECIFICATION: MAXIM PURITIES PPM:

Description	PPM	Description	PPM
Copper(Cu)	99,99	Cobalt(Co)	0,02
Iron(Fe)	0,02	Arsenic(As)	0,01
Silver(Ag)	0,02	Manganese(Mn)	0,01
Nickel(Ni)	0,002	Tellurium(Te)	0,002
Selenium(Se)	0,002	Aluminum(Al)	0,001
Antimony(Sb)	0,01	Magnesium(Mg)	0,001
Silica(Si)	0,001	Zinc(Zn)	0,001